

From: [Houston, Robert](mailto:Houston,Robert)
To: aj.hard@houston-solutions.com
Cc: Robert.Houston
Subject: Re: HC MUD 286 TX101252
Date: Thursday, September 7, 2017 9:38:45 AM

Robert Houston
Chief, Special Projects Section
Office: [214.665-8565](tel:214.665.8565)

Begin forwarded message:

From: "Bell, Cecil I MAJ" <Cecil.Bell@txsp.state.tx.us>
Date: September 7, 2017 at 9:04:51 AM CDT
To: "houston.robert@epa.gov" <houston.robert@epa.gov>
Subject: HC MUD 286 TX101252



1 Generator partially submerged. TX 101252 HC MUD 286



#2 of Generator partially submerged. TX 101252 HC MUD 286



#3 MCC partially submerged. TX 101252 HC MUD 286



#4 Watermark in building. TX 101252 HC MUD 286



#5 MCC partially submerged. TX 101252 HC MUD 286



#6 Disinfection building partially submerged. TX 101252 HC MUD 286



#7 Water well vent was submerged. TX 101252 HC MUD 286



MCC partially submerged. TX 101252 HC MUD 286

Sent from my iPhone